

Message

From: Bochenek, David [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=D9456788EF034B79A06044CE4AFA910A-BOCHENEK, DAVID]
Sent: 1/24/2017 9:44:04 PM
To: Wright, DavidA [/o=ExchangeLabs/ou=Exchange Administrative Group (FYDIBOHF23SPDLT)/cn=Recipients/cn=4f14a47c701547479b12bee35117d0a9-Wright, David A.]; Spieth, John [/o=ExchangeLabs/ou=Exchange Administrative Group (FYDIBOHF23SPDLT)/cn=Recipients/cn=7a48ef6030334c91bc8b660a14054aa0-Spieth, John]; Wilson, Dale [/o=ExchangeLabs/ou=Exchange Administrative Group (FYDIBOHF23SPDLT)/cn=Recipients/cn=bfa2e0da55ce443f940d17744e2382ba-Wilson, Dal]
CC: Mazaitis, Vincent [/o=ExchangeLabs/ou=Exchange Administrative Group (FYDIBOHF23SPDLT)/cn=Recipients/cn=3852485d8ac641d8ad91035a5de7c82b-Mazaitis, Vincent]; Cullen, Daniel [/o=ExchangeLabs/ou=Exchange Administrative Group (FYDIBOHF23SPDLT)/cn=Recipients/cn=0feb8e3bbb3943a9afc1cbe32e40e3bc-Cullen, Dan]
Subject: RE: GM Vehicle 161HPV4309

David,

Okay we will run their Battery Protection Procedure that you had supplied previously, followed by a UDDS prep and HWY warm-up/HWY sample test.

Thanks

Dave

From: Wright, DavidA
Sent: Tuesday, January 24, 2017 2:34 PM
To: Spieth, John <Spieth.John@epa.gov>; Bochenek, David <bochenek.david@epa.gov>
Cc: Mazaitis, Vincent <mazaitis.vincent@epa.gov>; Cullen, Daniel <Cullen.Daniel@epa.gov>
Subject: GM Vehicle 161HPV4309

John and Dave,

I believe GM Diesel Cruze vehicle 161HPV4309 is scheduled for a confirmatory highway test on this Friday. I believe the vehicle will possibly have been sitting for 10 days or more without having the engine started. If this is the case, the vehicle needs to be run through the pre-conditioning process previously forwarded to ensure the vehicle does not enter battery conditioning mode.

Let me know if you have any questions, or, need any additional information.

Thanks,

David